

## **April 2017 FISHWAY INSPECTION SUMMARY**

Fishway Inspections were conducted at most Columbia and Snake River Dams fitted with adult fish passage structures over April of 2017.

Overall, few problems were encountered and most fishways appeared to be in satisfactory or better operation. The few problems encountered are listed below.

Bonneville Dam (April 7, 2017): The A-branch ladder was flooded, PH1 collection channel velocity was slow, and the bulkheads in both spillway side entrances were banging around and overtopping.

McNary Dam (4-26-17): AWS Pump #2 was OOS.

Ice Harbor (4-27-17): The picking beam for the Northshore entrance was submerged at least 1 ft. in the entrance.

Wanapum Dam (4-25-17): Picketed leads at left bank count station were wide open.