

## **June 2010 FISHWAY INSPECTION SUMMARY**

Fishway Inspections were conducted at most Columbia and Snake River Dams fitted with adult fish passage structures over June of 2010.

Overall, few problems were encountered and most fishways appeared to be in satisfactory or better operation. The few problems encountered are listed below.

Lower Monumental Dam (June 25, 2010): Slightly low head differential at South Powerhouse entrance.

Lower Granite (June 22, 2010): Slightly low weir depth (0.9 ft).