

June 2015 FISHWAY INSPECTION SUMMARY

Fishway Inspections were conducted at all Columbia and Snake River Dams fitted with adult fish passage structures over June of 2015.

Overall, few problems were encountered and most fishways appeared to be in satisfactory or better operation. The few problems encountered are listed below.

Bonneville Dam (June 19, 2015): Bradford island Exit not clean, non-readable staff gauges. Low differentials at Washington Shore entrances, FV 5-4 OOS.

McNary Dam (June 17, 2015): Fish Pump #1 and #2 Out of Service.

Priest Rapids Dam (June 23, 2015): Fish Pump #2 Out of Service (several days).

Ice Harbor (June 25, 2015): Staff gauges not clean, tail water gauges out of calibration.

Lower Monumental (June 25, 2015): Velocity meter not working.

Lower Granite (June 26, 2015): Head differentials low at South and North shore.