

## **MARCH 2015 FISHWAY INSPECTION SUMMARY**

Fishway Inspections were conducted at several Columbia and Snake River Dams fitted with adult fish passage structures over March of 2015.

Overall, few problems were encountered and most fishways appeared to be in satisfactory or better operation. The few problems encountered are listed below.

Bonneville Dam (March 13, 2015): Weir Gate #1 was out of criteria due to failed gate. The PLC at the B-Branch fishway was not reading correctly. Non-readable staff gauges at Washington Shore Fishway.