

## **May 2011 FISHWAY INSPECTION SUMMARY**

Fishway Inspections were conducted at most Columbia and Snake River Dams fitted with adult fish passage structures over May of 2011.

Overall, few problems were encountered and most fishways appeared to be in satisfactory or better operation. The few problems encountered are listed below.

Bonneville Dam (May 27, 2011): Some large woody debris recorded at Washington Shore Exit.

McNary Dam (May 25, 2011): Washington Shore picketed leads and ladder exit were recorded as not clean.

Lower Granite Dam (May 18, 2011): Picketed leads not clean, low ladder weir depth (0.9 ft).