

May 2018 FISHWAY INSPECTION SUMMARY

Fishway Inspections were conducted at most Columbia and Snake River Dams fitted with adult fish passage structures over May of 2018.

Overall, few problems were encountered and most fishways appeared to be in satisfactory or better operation. The few problems encountered are listed below.

Bonneville (5-31-18): Several Washington Shore entrance below 1.0 foot head differential criteria.

Priest Rapids (5-24-18): LSE-2 entrance below head differential criteria.

Wells (5-24-18): Pump room on East Fishway flooded, causing pumps to be stuck at low level, causing little to no head differential at East Fishway.