

## **SEPTEMBER 2009 FISHWAY INSPECTION SUMMARY**

Fishway Inspections were conducted at all thirteen Columbia and Snake River Dams fitted with adult fish passage structures over September of 2009.

Overall, few problems were encountered and most fishways appeared to be in satisfactory or better operation. The few problems encountered are listed below.

Lower Monumental Dam (September 29, 2009): North and South shore exits needed some cleaning and SSE-1 weir depth not in criteria and weir gate not on sill.

Wells Dam (September 29, 2009): Head differential at East fishway slightly below criteria.