

## **September 2013 FISHWAY INSPECTION SUMMARY**

Fishway Inspections were conducted at all Columbia and Snake River Dams fitted with adult fish passage structures over September of 2013.

Overall, several problems were encountered but most fishways appeared to be in satisfactory or better operation. The few problems encountered are listed below.

Bonneville Dam (September 26, 2013): Head differential at B-branch below criteria, at the Washington Shore fishway entrance head differential below criteria at the South Downstream Entrance (SDE).

Lower Granite Dam (September 27, 2013): Entrance head differentials at NPE and NSE did not meet minimum criteria.