

Table 9. Pertinent Data for Fish Facility Inspections in 2014 at PRIEST RAPIDS DAM.										
CRITERIA ITEMS										
		DATE OF INSPECTION								
LEFT BANK FISHWAY		<u>15-Apr</u>	<u>15-May</u>	<u>21-May</u>	<u>15-Jun</u>	<u>23-Jul</u>	<u>31-Jul</u>	<u>27-Aug</u>	<u>14-Sep</u>	<u>23-Sep</u>
<i>Left Bank Entrance:</i>										
<u>Head at main entrances (Criteria = 1-2 ft)</u>										
LSE-2 (1.2 ft target)	ft	1.5	1.3	2.0	1.7	1.4	1.4	1.7	1.4	1.5
LSE-4 (1.5 ft target)	ft	1.4	1.3	1.6	1.5	1.6	1.8	1.4	1.5	1.4
Depth over ladr. weir (Crit. = 1-1.2 ft)	ft	1.1	1.1	1.1	1.0	1.1	1.1	1.0	1.0	1.0
Water velocity (Crit. = 1.5-4 fps)	fps	2.3	>1.5	2.0	>2.0	2.2	>1.5	1.2	1.1	2.0
Ladder exit clean (Crit. = yes or no)		yes	yes	yes	yes	yes	yes	yes	yes	yes
Staff gages clean (Crit. = yes or no)		yes	yes	yes	yes	yes	yes	yes	yes	yes
RIGHT BANK FISHWAY										
<i>Right Bank Entrance:</i>										
<u>Head at Entrance (Criteria = 1-2 ft)</u>										
RSE-1 (1.5 ft target)	ft	0.3	1.5	1.4	1.6	1.5	1.5	1.5	1.5	1.4
Depth over ladr. weir (Crit. = 1-1.2 ft)	ft	NA	1.0	1.0	1.0	1.0	1.0	1.0	1.1	1.0
Ladder exit clean (Crit. = yes or no)		NA	yes	yes	yes	yes	yes	yes	yes	yes
Staff gages clean (Crit. = yes or no)		yes	yes	yes	yes	yes	yes	yes	yes	yes
Comment number (if applicable)		1								
Comments:										
1. Rightbank ladder at orifice flow due to trap operations, no water at exit or count station at orifice flow, recommended going to ladder flow with gravity forebay water, GCPUD switched to ladder flow at 3:22 pm.										