

**Table10. Pertinent Data for Fish Facility Inspections in 2015 at WANAPUM DAM.**

CRITERIA		DATE OF INSPECTION						
		<u>29-Apr</u>	<u>12-May</u>	<u>23-Jun</u>	<u>30-Jul</u>	<u>26-Aug</u>	<u>17-Sep</u>	<u>28-Oct</u>
<b>LEFT BANK FISHWAY</b>								
<i>Left Bank Entrance:</i>								
<b><u>Head at entrances (Criteria = 1-2 ft)</u></b>								
LSE-2 (target head = 1.5 ft)	ft	1.5	1.7	1.0	1.6	1.6	1.6	1.8
LSE-3 (target head = 1.2 ft)	ft	1.5	1.7	1.6	1.6	1.7	1.4	1.7
Dep. over ladr. weir (Crit. = 1.0-1.2ft)	ft	1.0	1.0	1.0	1.0	1.1	1.1	1.1
Channel velocity (Crit. = 1.5-4.0 fps)	fps	2.0	2.0	2.5	2.5	2.2	1.8	2.2
Staff gages clean (Crit. = yes or no)		yes	yes	yes	yes	yes	yes	yes
Auxiliary H2O Pumps	rpm	109/120	128/138	131/138	0/140	0/156	0/151	0/159
Ladder exit clean (Crit. = yes or no)		yes	yes	yes	yes	yes	no	yes
<b>RIGHT BANK FISHWAY</b>								
<i>Right Bank Entrance:</i>								
<b><u>Head at Entrance (Criteria = 1-2 ft)</u></b>								
RSE-2 (target head = 1.2 ft)	ft	1.5	1.6	1.5	1.5	1.6	1.7	1.7
Depth over ladder weir	ft	1.0	1.0	1.0	1.0	1.1	1.0	1.1
Ladder exit clean		yes	yes	yes	yes	yes	yes	yes
Staff gages clean		yes	yes	yes	yes	yes	yes	yes
Comment number (if applicable)							1	
<b>Comments:</b>								
1. Left exit had many tumbleweds, GCPUD to clean ASAP.								

