

APRIL 2009 FISHWAY INSPECTION SUMMARY

Fishway Inspections were conducted at most Columbia and Snake River Dams fitted with adult fish passage structures over April of 2009.

Overall, few problems were encountered and most fishways appeared to be in satisfactory or better operation. The few problems encountered are listed below.

Bonneville Dam (April 16, 2009): Depth over weir was below criteria at the following locations: Bradford, A-Branch, B-Branch, and Weir 67. Bradford exit needed cleaning.

The Dalles Dam (April 30, 2009): Depth over North shore weir slightly below criteria.

Rock Island Dam (April 28, 2009): Several right bank head differentials out of criteria.