

April 2013 FISHWAY INSPECTION SUMMARY

Fishway Inspections were conducted at most Columbia and Snake River Dams fitted with adult fish passage structures over April of 2013.

Overall, few problems were encountered and most fishways appeared to be in satisfactory or better operation. The few problems encountered are listed below.

The Dalles Dam (April 25, 2013): North Shore depth over ladder weir below criteria.

McNary Dam (April 26, 2013): AWS Pump #2 Out of Service, Washington shore exit not clean.

Little Goose Dam (April 16, 2013): AWS Pump #3 Out of Service as result NPE-2 entrance gate closed. North shore entrance gates inoperable and fixed at 532 feet.