

AUGUST 2009 FISHWAY INSPECTION SUMMARY

Fishway Inspections were conducted at all thirteen Columbia and Snake River Dams fitted with adult fish passage structures over August of 2009.

Overall, few problems were encountered and most fishways appeared to be in satisfactory or better operation. The one problem encountered is listed below.

McNary Dam (August 31, 2009): Head differential at NFEW1 and NFEW2 were both below criteria and North shore picketed leads needed cleaning.