

## **August 2012 FISHWAY INSPECTION SUMMARY**

Fishway Inspections were conducted at all Columbia and Snake River Dams fitted with adult fish passage structures over August of 2012.

Several problems were encountered over August 2012, problems encountered are listed below.

Bonneville Dam (August 3, 2012): Cascade Island Tailwater gauge missing, computer reading incorrect.

McNary Dam (August 29, 2012): Below gate depth criteria at the south shore fishway due to only two available fish pumps.

Lower Granite Dam (August 25, 2012): Fishway exit not clean.