

August 2014 FISHWAY INSPECTION SUMMARY

Fishway Inspections were conducted at most Columbia and Snake River Dams fitted with adult fish passage structures over August of 2014.

Overall, few problems were encountered and most fishways appeared to be in satisfactory or better operation. The few problems encountered are listed below.

McNary Dam (August 20, 2014): One-half of Floating Orifice Gates were stuck and overtopping, AWS Pump #2 Out of Service.

Wanapum Dam (August 20, 2014): Modified ladder operations due to spillway crack and reservoir drawdown, milfoil causing pumps to clog every few days.

Wells Dam (August 14, 2014): Several staff gauges not clean.

Ice Harbor Dam (August 23, 2014): Several staff gauges not clean, velocity meter not working.