

August 2015 FISHWAY INSPECTION SUMMARY

Fishway Inspections were conducted at all Columbia and Snake River Dams fitted with adult fish passage structures over August of 2015.

Overall, few problems were encountered and most fishways appeared to be in satisfactory or better operation. The few problems encountered are listed below.

Bonneville Dam (August 17, 2015): Staff gauges not clean, FV 5-4 OOS. Cascade Island Entrances had low head differential.

McNary Dam (August 27, 2015): Oregon Shore picketed leads not clean.

Wells Dam (August 26, 2015): Staff gauges dirty

Lower Monumental (August 25, 2015): Velocity meter not working.

Lower Granite (August 31, 2015): No attraction lighting seen in tunnel to Northshore.