

## **July 2014 FISHWAY INSPECTION SUMMARY**

Fishway Inspections were conducted at most Columbia and Snake River Dams fitted with adult fish passage structures over July of 2014.

Overall, few problems were encountered and most fishways appeared to be in satisfactory or better operation. The few problems encountered are listed below.

McNary Dam (July 30, 2014): Floating orifice gate #14 was stuck and overtopping, AWS Pump #2 Out of Service.

Wanapum Dam (July 2 and 23, 2014): Modified ladder operations due to spillway crack and reservoir drawdown.