

June 2014 FISHWAY INSPECTION SUMMARY

Fishway Inspections were conducted at most Columbia and Snake River Dams fitted with adult fish passage structures over June of 2014.

Overall, few problems were encountered and most fishways appeared to be in satisfactory or better operation. The few problems encountered are listed below.

Bonneville Dam (June 20, 2014): Multiple staff gauges broken/missing.

McNary Dam (June 27, 2014): Floating orifice gate #14 was stuck and overtopping, AWS Pump #2 Out of Service.

Lower Monumental Dam (June 28, 2014): NSE 1&2 head differential below criteria.

Lower Granite Dam (June 26, 2014): NPE 1&2 head differential slightly below criteria.

Wanapum Dam (June 4 and 15, 2014): Modified ladder operations due to spillway crack and reservoir drawdown.