

May 2014 FISHWAY INSPECTION SUMMARY

Fishway Inspections were conducted at most Columbia and Snake River Dams fitted with adult fish passage structures over May of 2014.

Overall, few problems were encountered and most fishways appeared to be in satisfactory or better operation. The few problems encountered are listed below.

Bonneville Dam (May 9, 2014): Multiple staff gauges broken/missing, Bradford Island exit not clean.

McNary Dam (May 30, 2014): Floating orifice gate #14 was stuck and overtopping, AWS Pump #2 Out of Service.

Lower Granite Dam (May 30, 2014): NPE 1&2 did not meet head differential criteria.

Wanapum Dam (May 7 and 21, 2014): Modified ladder operations due to spillway crack and reservoir drawdown.