

May 2015 FISHWAY INSPECTION SUMMARY

Fishway Inspections were conducted at all Columbia and Snake River Dams fitted with adult fish passage structures over May of 2015.

Overall, few problems were encountered and most fishways appeared to be in satisfactory or better operation. The few problems encountered are listed below.

Bonneville Dam (May 8, 2015): Weir Gate #1 on sill causing Bradford Island weirs to be incorrect. FV 5-4 Out of Service.

Little Goose Dam (May 30, 2015): NPE entrance gates out of criteria- gates not on sill.

Priest Rapids Dam (May 12, 2015): Fish Pump #1 Out of Service, will be back in service in few days.