

October 2013 FISHWAY INSPECTION SUMMARY

Fishway Inspections were conducted at all Columbia and Snake River Dams fitted with adult fish passage structures over October of 2013.

Overall, several problems were encountered but most fishways appeared to be in satisfactory or better operation. The few problems encountered are listed below.

Bonneville Dam (October 25, 2013): The Washington Shore fishway exit was not clean.

The Dalles Dam (October 28, 2013): East entrance head differential below criteria.

Lower Monumental Dam (October 28, 2013): Head differential at North Shore picketed leads greater than maximum criteria.

Lower Granite Dam (October 31, 2013): Entrance head differentials at NPE and NSE did not meet minimum criteria.