

## **October 2015 FISHWAY INSPECTION SUMMARY**

Fishway Inspections were conducted at all Columbia and Snake River Dams fitted with adult fish passage structures over October of 2015.

Overall, few problems were encountered and most fishways appeared to be in satisfactory or better operation. The few problems encountered are listed below.

Bonneville Dam (October 9, 2015): FV 5-4 being worked on, Cascades Island at orifice flow, some issue with fish jumping when UMT closed, staff gauges unreadable.

McNary Dam (October 28, 2015): Several orifice gates removed for overhaul, one sticking.

Rock Island Dam (October 28, 2015): Pump #3 out of service, unable to meet entrance head criteria at Right bank fishway.

Lower Monumental (October 15, 2015): Velocity meter not working.

Lower Granite (October 23, 2015): No attraction lighting seen in tunnel to Northshore.