

**Table 9. Pertinent Data for Fish Facility Inspections in 2008 at PRIEST RAPIDS DAM.**

<b>CRITERIA ITEMS</b>	<b>DATE OF INSPECTION</b>							
	<b>24-Apr</b>	<b>22-May</b>	<b>26-Jun</b>	<b>24-Jul</b>	<b>28-Aug</b>	<b>18-Sep</b>	<b>24-Oct</b>	
<b>LEFT BANK FISHWAY</b>								
<i>Left Bank Entrance:</i>								
<b>Head at main entrances (Criteria = 1-2 ft)</b>								
LSE-2 (1.2 ft target)	ft	1.4	1.5	1.7	1.7	1.2	1.4	1.5
LSE-4 (1.5 ft target)	ft	1.5	1.2	1.1	1.6	1.6	1.5	1.5
Depth over ladr. weir (Crit. = 1-1.2 ft)	ft	1.1	1.0	1.1	1.0	1.1	1.1	1.0
Water velocity (Crit. = 1.5-4 fps)	fps	>1.5	2.4	2.2	2.0	1.9	1.8	1.7
Ladder exit clean (Crit. = yes or no)		yes	yes	yes	yes	yes	yes	yes
Staff gages clean (Crit. = yes or no)		yes	yes	yes	yes	yes	yes	yes
<b>RIGHT BANK FISHWAY</b>								
<i>Right Bank Entrance:</i>								
<b>Head at Entrance (Criteria = 1-2 ft)</b>								
RSE-1 (1.5 ft target)	ft	1.3	1.4	1.5	1.5	1.3	1.4	1.5
Depth over ladr. weir (Crit. = 1-1.2 ft)	ft	1.1	1.1	1.1	1.2	1.2	1.2	1.1
Ladder exit clean (Crit. = yes or no)		yes	yes	yes	yes	yes	yes	yes
Staff gages clean (Crit. = yes or no)		yes	yes	yes	yes	yes	yes	yes
Comment number (if applicable)		1	2	3				4
<b>Comments:</b>								
1. One aux. Pump is inoperative due to needed maintenance								
2. GIG no longer functions automatically- GCPUD is working on a fix.								
3. GIG still set in fixed position, velocity meter not working (visually estimated).								
4. GIG fixed but leaking some hydraulic fluid from RAM.								