

## **September 2012 FISHWAY INSPECTION SUMMARY**

Fishway Inspections were conducted at all Columbia and Snake River Dams fitted with adult fish passage structures over September of 2012.

Several problems were encountered and over September 2012, problems encountered are listed below.

McNary Dam (September 20, 2012): Below gate depth criteria at the south shore fishway due to only two available fish pumps.

Lower Granite Dam (September 27, 2012): Fishway exit not clean.