

Table 9. Pertinent Data for Fish Facility Inspections in 2013 at PRIEST RAPIDS DAM.

CRITERIA ITEMS		DATE OF INSPECTION						
LEFT BANK FISHWAY		<u>23-Apr</u>	<u>14-May</u>	<u>25-Jun</u>	<u>24-Jul</u>	<u>22-Aug</u>	<u>18-Sep</u>	<u>23-Oct</u>
<i>Left Bank Entrance:</i>								
<u>Head at main entrances (Criteria = 1-2 ft)</u>								
LSE-2 (1.2 ft target)	ft	1.5	1.5	1.2	1.6	1.5	1.6	1.1
LSE-4 (1.5 ft target)	ft	1.5	1.4	1.6	1.6	1.5	1.4	1.3
Depth over ladr. weir (Crit. = 1-1.2 ft)	ft	1.1	1.1	1.1	1.1	1.1	1.0	1.1
Water velocity (Crit. = 1.5-4 fps)	fps	2.5	1.8	1.5	1.9	1.2	1.6	2.0
Ladder exit clean (Crit. = yes or no)		yes	yes	yes	yes	yes	yes	yes
Staff gages clean (Crit. = yes or no)		yes	yes	yes	yes	yes	yes	yes
RIGHT BANK FISHWAY								
<i>Right Bank Entrance:</i>								
<u>Head at Entrance (Criteria = 1-2 ft)</u>								
RSE-1 (1.5 ft target)	ft	1.5	0.9	1.5	1.5	1.5	1.4	1.5
Depth over ladr. weir (Crit. = 1-1.2 ft)	ft	1.1	1.1	1.0	1.0	1.1	1.0	1.1
Ladder exit clean (Crit. = yes or no)		yes	yes	yes	yes	yes	yes	yes
Staff gages clean (Crit. = yes or no)		yes	yes	yes	yes	yes	yes	yes
Comment number (if applicable)			1					
Comments:								
1. No access to right bank fishway, data obtained from control room.								