

**Table 11. Pertinent Data for Fish Facility Inspections in 2012 at ROCK ISLAND DAM**

<b>CRITERIA ITEMS</b>		<b>DATE OF INSPECTION</b>						
		<b>18-Apr</b>	<b>16-May</b>	<b>27-Jun</b>	<b>25-Jul</b>	<b>29-Aug</b>	<b>26-Sep</b>	<b>24-Oct</b>
<b>LEFT BANK FISHWAY</b>								
<b>Left Bank Entrance:</b>								
Depth over entrance weir								
LO5 (Criteria = 6.0 ft or >)	ft	7.1	6.5	7.2	6.7	6.9	6.8	6.7
LO6 (Criteria = 6.0 ft or >)	ft	7.2	6.5	7.6	7.1	6.6	7.0	6.7
Head at LO5 & 6 (Crit. = 1-2 ft)	ft	1.1	1.7	1.2	1.1	1.2	1.0	1.4
Depth over ladder weir	ft	1.1	1.1	1.0	1.1	1.1	1.1	1.1
(Criteria = 1.0-1.2 ft)								
Staff gages clean (yes or no)		yes	yes	yes	yes	yes	yes	yes
Ladder exit clean (yes or no)		yes	yes	yes	yes	yes	yes	yes
Picket leads clean (yes or no)		yes	yes	yes	yes	yes	yes	yes
<b>CENTER FISHWAY</b>								
<b>Center Entrance:</b>								
Depth over entrance weir								
MO3 (Criteria = 8.5 ft or >)	ft	8.9	9.0	11.8	9.5	8.8	8.9	9.0
Head at MO3 (Criteria = 1-2 ft)	ft	1.3	1.2	1.0	1.4	1.5	1.2	1.3
Depth over ladder weir	ft	1.1	1.1	1.1	1.1	1.1	1.1	1.1
(Criteria = 1.0-1.2 ft)								
Ladder exit clean (yes or no)		yes	yes	yes	yes	yes	yes	yes
Picket leads clean (yes or no)		yes	yes	yes	yes	yes	yes	yes
<b>RIGHT BANK FISHWAY</b>								
<b>Right Bank Entrance:</b>								
Head Differential (Crit. = 1-2 ft)								
LPE-1	ft	1.0	1.0	0.8	1.1	1.1	1.3	1.3
RPE-1 and RPE-2	ft	closed/1.7	closed/1.6	closed/1.1	closed/1.5	1.1/1.1	1.4	1.4
TPE	ft	1.2	1.1	0.7	1.2	1.2	1.4	1.4
Depth over ladder weir	ft	1.1	1.1	1.1	1.1	1.1	1.3	1.1
(Criteria = 1.0-1.2 ft)								
Channel veloc(Cr. = 1.5-4 fps)	fps	3.9	3.7	3.9	4.2	4.1	3.8	4.0
Ladder exit clean (yes or no)		yes	yes	yes	yes	yes	yes	yes
Picket leads clean (yes or no)		yes	yes	yes	yes	yes	yes	yes
Pumps operating		3	3	3	3	3	3	3
Pump Gate Openings	%	44-97%	93-98%	96-100%	78-99%	92-100%	41-93%	90-99%
Comment number (if applicable)		1	1	2	1			
<b>Comments:</b>								
1. RPE1 closed due to high flows.								
2. High water impacting ability to meet target differentials.								