

Table 11. Pertinent Data for Fish Facility Inspections in 2009 at ROCK ISLAND DAM

CRITERIA ITEMS		DATE OF INSPECTION						
		28-Apr	27-May	25-Jun	21-Jul	26-Aug	23-Sep	21-Oct
LEFT BANK FISHWAY								
Left Bank Entrance:								
Depth over entrance weir								
LO5 (Criteria = 6.0 ft or >)	ft	6.8	6.8	6.7	6.9	6.5	6.7	6.3
LO6 (Criteria = 6.0 ft or >)	ft	6.8	6.7	6.5	6.8	6.5	6.8	6.7
Head at LO5 & 6 (Crit. = 1-2 ft)	ft	1.4	1.2	1.4	1.2	1.2	1.1	1.2
Depth over ladder weir (Criteria = 1.0-1.2 ft)	ft	1.0	1.1	1.0	1.0	1.0	1.1	1.1
Staff gages clean (yes or no)		yes	yes	yes	yes	yes	yes	yes
Ladder exit clean (yes or no)		yes	yes	yes	yes	yes	yes	yes
Picket leads clean (yes or no)		yes	yes	yes	yes	yes	yes	yes
CENTER FISHWAY								
Center Entrance:								
Depth over entrance weir								
MO3 (Criteria = 8.5 ft or >)	ft	8.6	8.7	8.5	8.9	8.8	8.8	8.5
Head at MO3 (Criteria = 1-2 ft)	ft	1.2	1.4	1.3	1.2	1.3	1.4	1.4
Depth over ladder weir (Criteria = 1.0-1.2 ft)	ft	1.0	1.1	1.0	1.0	1.0	1.1	1.1
Ladder exit clean (yes or no)		yes	yes	yes	yes	yes	yes	yes
Picket leads clean (yes or no)		yes	yes	yes	yes	yes	yes	yes
RIGHT BANK FISHWAY								
Right Bank Entrance:								
Head Differential (Crit. = 1-2 ft)								
LPE-1	ft	0.9	0.9	1.3	1.1	1.2	1.2	1.3
RPE-1 and RPE-2	ft	1.1	1.0	1.6	1.5	1.6	1.5	1.3
TPE	ft	0.7	0.7	1.2	0.9	1.5	1.3	1.2
Depth over ladder weir (Criteria = 1.0-1.2 ft)	ft	1.0	1.1	0.5	1.0	1.0	1.1	1.5
Channel veloc(Cr. = 1.5-4 fps)	fps	4.2	3.8	3.6	3.8	2.7	3.7	*
Ladder exit clean (yes or no)		yes	yes	yes	yes	yes	yes	yes
Picket leads clean (yes or no)		yes	yes	yes	yes	yes	yes	yes
Pumps operating		3	3	3	3	3	3	3
Pump Gate Openings	%	100	100	51.8-98.1	96	73-100	94-95	27.7-97.5
Comment number (if applicable)				1				2
Comments:								
1. RPE-1 closed, RO3 broken depth over ladder weir on rght bank low- working on fix for RO3								
2. RPE-1 back open								
3, Could not obtain velocity- low battery in meter.								