

**Table10. Pertinent Data for Fish Facility Inspections in 2016 at WANAPUM DAM.**

<b>CRITERIA</b>								
		<u>DATE OF INSPECTION</u>						
		<u>26-Apr</u>	<u>24-May</u>	<u>23-Jun</u>	<u>27-Jul</u>	<u>24-Aug</u>	<u>28-Sep</u>	<u>25-Oct</u>
<b>LEFT BANK FISHWAY</b>								
<i>Left Bank Entrance:</i>								
<b>Head at entrances (Criteria = 1-2 ft)</b>								
LSE-2 (target head = 1.5 ft)	ft	1.6	1.4	1.6	1.7	1.9	1.5	1.4
LSE-3 (target head = 1.2 ft)	ft	1.7	1.6	1.8	1.5	1.4	1.2	1.6
Dep. over ladr. weir (Crit. = 1.0-1.2ft)	ft	1.0	1.1	1.1	1.1	1.0	1.0	1.1
Channel velocity (Crit. = 1.5-4.0 fps)	fps	1.8	1.9	2.2	2.0	2.0	2.0	1.3
Staff gages clean (Crit. = yes or no)		yes	yes	yes	yes	yes	yes	yes
Auxiliary H2O Pumps	rpm	99/0	135/141	138/141	136/137	117/139	99/102	97/102
Ladder exit clean (Crit. = yes or no)		yes	yes	yes	yes	yes	yes	yes
<b>RIGHT BANK FISHWAY</b>								
<i>Right Bank Entrance:</i>								
<b>Head at Entrance (Criteria = 1-2 ft)</b>								
RSE-2 (target head = 1.2 ft)	ft	1.6	1.5	1.7	1.4	1.6	1.6	1.5
Depth over ladder weir	ft	1.1	1.1	1.0	1.1	1.0	1.0	1.1
Ladder exit clean		yes	yes	yes	yes	yes	yes	yes
Staff gages clean		yes	yes	yes	yes	yes	yes	yes
Comment number (if applicable)								
<b>Comments:</b>								