

April 2015 FISHWAY INSPECTION SUMMARY

Fishway Inspections were conducted at all Columbia and Snake River Dams fitted with adult fish passage structures over April of 2015.

Overall, few problems were encountered and most fishways appeared to be in satisfactory or better operation. The few problems encountered are listed below.

Bonneville Dam (April 10, 2015): Weir Gate #1 still not operating correctly. B-Branch south entrance gate open- north gate should be open at current tailwater.

Ice Harbor Dam (April 14, 2015): Computer readings do not match visual observations at North Shore and North Powerhouse, dirty staff gauges.

Lower Monumental Dam (April 15, 2015): Dirty staff gauges.

Little Goose Dam (April 15, 2015): Fish Pump #1 Out of Service, FCS control not working well (system in manual).

Lower Granite Dam (April 25, 2015): Loud knocking at NPE, mild eddy at SSE.