

July 2015 FISHWAY INSPECTION SUMMARY

Fishway Inspections were conducted at all Columbia and Snake River Dams fitted with adult fish passage structures over July of 2015.

Overall, few problems were encountered and most fishways appeared to be in satisfactory or better operation. The few problems encountered are listed below.

Bonneville Dam (July 17, 2015): Staff gauges not clean, FV 5-4 OOS.

Wells Dam (July 22, 2015): Staff gauges dirty.

Lower Monumental (July 30, 2015): Velocity meter not working.

Lower Granite (July 30, 2015): No attraction lighting seen in tunnel to Northshore.