

### **March 2017 FISHWAY INSPECTION SUMMARY**

Fishway Inspections were conducted at the three lowest Columbia River Dams fitted with adult fish passage structures over March of 2017.

Overall, very few problems were encountered and most fishways appeared to be in satisfactory or better operation. The problems encountered are listed below.

John Day Dam (March 21, 2017): South Fish Pump 1 was OOS.