

May 2012 FISHWAY INSPECTION SUMMARY

Fishway Inspections were conducted at most Columbia and Snake River Dams fitted with adult fish passage structures over May of 2012.

Overall, few problems were encountered and most fishways appeared to be in satisfactory or better operation. The few problems encountered are listed below.

The Dalles Dam (May 22, 2012): East ladder exit was not clean.

Lower Monumental Dam (May 22, 2012): Some debris at North Shore ladder exit.

Lower Granite Dam (May 22, 2012): Channel lights not functioning.