

June 2013 FISHWAY INSPECTION SUMMARY

Fishway Inspections were conducted at all Columbia and Snake River Dams fitted with adult fish passage structures over June of 2013.

Overall, minor problems were encountered and most fishways appeared to be in satisfactory or better operation. The few problems encountered are listed below.

Little Goose Dam (June 18, 2013): AWS Pump #3 Out of Service as result NPE-2 entrance gate closed. North shore entrance gates inoperable and fixed at 532 feet.