

## **September 2016 FISHWAY INSPECTION SUMMARY**

Fishway Inspections were conducted at all Columbia and Snake River Dams fitted with adult fish passage structures over September of 2016.

Overall, few problems were encountered and most fishways appeared to be in satisfactory or better operation. The problems encountered are listed below.

Bonneville Dam (September 9, 2016): The tailwater staff gauges at Bradford Island and Cascade island were not visible.