

Table 3. Pertinent Data for Fish Facility Inspections in 2015 at JOHN DAY DAM.

CRITERIA ITEMS		DATE OF INSPECTION						
		24-Mar	28-Apr	29-May	23-Jun	4-Aug	24-Sep	26-Oct
SOUTH SHORE FISHWAY								
South Shore Entrance:								
Depth over entrance weir								
SE-1 (Crit. = 8 ft or >)	ft	8.4	8.8	9.4	9.6	9.5	9.1	8.4
Head at SE-1 (Crit. = 1-2 ft)	ft	1.4	1.3	1.2	1.6	1.5	1.7	1.4
Dep. over ladr. weir (Crit.=1.0 +/-0.1) ft [normal] & 1.3 ft shad season)	ft	1.0	1.0	1.2	1.2	1.0	1.0	1.0
Ladder exit clean (Yes or No)		yes	yes	yes	yes	yes	yes	yes
Staff gages clean (Yes or No)		yes	yes	yes	yes	yes	yes	yes
Picket Leads Clean (Yes or No)		yes	yes	yes	yes	yes	yes	yes
Pumps operating		3	3	3	3	3	3	3
Rpm for pumps		60	58/59	57	58	55	58	58
North Powerhouse Entrance:								
Depth over entrance weir								
NE-1 (Crit. = 8 ft or >)	ft	8.2	8.8	9.4	8.6	6.7	8.2	8.2
NE-2 (Crit. = 8 ft or >)	ft	8.2	8.9	9.2	8.5	8.7	8.3	8.1
Head at NE-1&2 (Crit. = 1-2 ft)	ft	1.5	1.5	1.5	1.5	1.4	1.3	1.2
Staff gages clean (yes or no)		yes	yes	yes	yes	yes	yes	yes
NORTH SHORE FISHWAY								
North Shore Entrance:								
Depth over entrance weir								
N-1 (Crit. = 8 ft or >)	ft	fixed	fixed	fixed	fixed	fixed	fixed	fixed
Head at N-1(Crit. = 1-2 ft) Targ - 1.5'	ft	1.5	1.5	1.5	1.5	1.5	1.5	1.6
Depth over ldr weir (Crit.=1.0 +/-0.1)	ft	1.0	1.0	1.2	1.3	1.0	1.0	1.1
Ladder exit clean		yes	yes	yes	yes	yes	yes	yes
Staff gages clean		yes	yes	yes	yes	yes	yes	yes
Picket leads clean		yes	yes	yes	yes	yes	yes	yes
Pumps Operating		4	3	3	3	3	3	3
Comment number (if applicable)						1		
Comments:								
1. NE-1 out of criteria due to ongoing adjustments being made.								