

**Table 3. Pertinent Data for Fish Facility Inspections in 2017 at JOHN DAY DAM.**

<b>CRITERIA ITEMS</b>		<b>DATE OF INSPECTION</b>			
		<b>21-Mar</b>	<b>25-Apr</b>	<b>23-May</b>	<b>22-Jun</b>
<b>SOUTH SHORE FISHWAY</b>					
<b>South Shore Entrance:</b>					
Depth over entrance weir					
SE-1 (Crit. = 8 ft or >)	ft	8.2	8.4	8.1	8.0
Head at SE-1 (Crit. = 1-2 ft)	ft	1.0	1.5	1.2	1.6
Dep. over ladr. weir (Crit.=1.0 +/-0.1)		1.1	1.0	1.0	1.3
ft [normal] & 1.3 ft shad season)	ft				
Ladder exit clean (Yes or No)		yes	yes	yes	yes
Staff gages clean (Yes or No)		yes	yes	yes	yes
Picket Leads Clean (Yes or No)		yes	yes	yes	yes
Pumps operating		2	2	2	2
Rpm for pumps		68	68	68	68
<b>North Powerhouse Entrance:</b>					
Depth over entrance weir					
NE-1 (Crit. = 8 ft or >)	ft	8.4	10.3	11.3	9.6
NE-2 (Crit. = 8 ft or >)	ft	8.4	10.1	11.2	9.5
Head at NE-1&2 (Crit. = 1-2 ft)	ft	2	1.8	1.9	1.9
Staff gages clean (yes or no)		yes	yes	yes	yes
<b>NORTH SHORE FISHWAY</b>					
<b>North Shore Entrance:</b>					
Depth over entrance weir					
N-1 (Crit. = 8 ft or >)	ft	fixed	fixed	fixed	fixed
Head at N-1(Crit. = 1-2 ft) Targ - 1.5'	ft	1.6	1.6	1.6	1.5
Depth over ldr weir (Crit.=1.0 +/-0.1)	ft	1.2	1.1	1.2	1.5
Ladder exit clean		yes	yes	yes	yes
Staff gages clean		yes	yes	yes	yes
Picket leads clean		yes	yes	yes	yes
Pumps Operating		4	3	4	3
Comment number (if applicable)		1	1	1	1
<b>Comments:</b>					
1. Pump #1 OOS on South Shore.					