

Table 9. Pertinent Data for Fish Facility Inspections in 2010 at PRIEST RAPIDS DAM.

CRITERIA ITEMS

LEFT BANK FISHWAY		DATE OF INSPECTION			
		<u>6-May</u>	<u>24-Jun</u>	<u>27-Jul</u>	<u>14-Sep</u>
<i>Left Bank Entrance:</i>					
Head at main entrances (Criteria = 1-2 ft)					
LSE-2 (1.2 ft target)	ft	1.9	1.5	1.3	1.5
LSE-4 (1.5 ft target)	ft	1.8	1.5	1.3	1.9
Depth over ladr. weir (Crit. = 1-1.2 ft)	ft	1.1	1.1	1.0	1.1
Water velocity (Crit. = 1.5-4 fps)	fps	1.5	na	3.2	1.5
Ladder exit clean (Crit. = yes or no)		yes	yes	yes	yes
Staff gages clean (Crit. = yes or no)		yes	yes	yes	yes

RIGHT BANK FISHWAY

Right Bank Entrance:

Head at Entrance (Criteria = 1-2 ft)

RSE-1 (1.5 ft target)	ft	1.8	1.6	1.3	1.6
Depth over ladr. weir (Crit. = 1-1.2 ft)	ft	1.1	1.1	1.1	1.2
Ladder exit clean (Crit. = yes or no)		yes	yes	yes	yes
Staff gages clean (Crit. = yes or no)		yes	yes	yes	yes
Comment number (if applicable)		1			

Comments:

1