

Table 9. Pertinent Data for Fish Facility Inspections in 2011 at PRIEST RAPIDS DAM.

CRITERIA ITEMS

		<u>DATE OF INSPECTION</u>						
		<u>27-Apr</u>	<u>19-May</u>	<u>30-Jun</u>	<u>27-Jul</u>	<u>31-Aug</u>	<u>20-Sep</u>	<u>26-Oct</u>
LEFT BANK FISHWAY								
<i>Left Bank Entrance:</i>								
<u>Head at main entrances (Criteria = 1-2 ft)</u>								
LSE-2 (1.2 ft target)	ft	1.4	1.2	1.3	1.4	1.4	1.6	1.4
LSE-4 (1.5 ft target)	ft	1.6	1.3	1.5	1.3	1.6	1.5	1.5
Depth over ladr. weir (Crit. = 1-1.2 ft)	ft	1.1	1.1	1.1	1.1	1.1	1.1	1.1
Water velocity (Crit. = 1.5-4 fps)	fps	1.9	1.9	2.2	2.0	1.7	1.5	1.0
Ladder exit clean (Crit. = yes or no)		yes	yes	yes	yes	yes	yes	yes
Staff gages clean (Crit. = yes or no)		yes	yes	yes	yes	yes	yes	yes
RIGHT BANK FISHWAY								
<i>Right Bank Entrance:</i>								
<u>Head at Entrance (Criteria = 1-2 ft)</u>								
RSE-1 (1.5 ft target)	ft	1.5	1.5	1.2	1.2	1.3	1.3	1.4
Depth over ladr. weir (Crit. = 1-1.2 ft)	ft	1.1	1.1	1.1	1.1	1.1	1.2	1.1
Ladder exit clean (Crit. = yes or no)		yes	yes	yes	yes	yes	yes	yes
Staff gages clean (Crit. = yes or no)		yes	yes	yes	yes	yes	yes	yes
Comment number (if applicable)								
Comments:								