

Table 9. Pertinent Data for Fish Facility Inspections in 2012 at PRIEST RAPIDS DAM.

CRITERIA ITEMS

LEFT BANK FISHWAY		<u>DATE OF INSPECTION</u>					
		<u>14-May</u>	<u>28-Jun</u>	<u>25-Jul</u>	<u>29-Aug</u>	<u>25-Sep</u>	<u>25-Oct</u>
<i>Left Bank Entrance:</i>							
<u>Head at main entrances (Criteria = 1-2 ft)</u>							
LSE-2 (1.2 ft target)	ft	1.3	1.4	1.4	1.4	1.4	1.5
LSE-4 (1.5 ft target)	ft	1.4	1.5	1.5	1.4	1.5	1.4
Depth over ladr. weir (Crit. = 1-1.2 ft)	ft	1.1	1.1	1.1	1.1	1.0	1.0
Water velocity (Crit. = 1.5-4 fps)	fps	2.0	2.1	2.0	2.0	2.0	1.2
Ladder exit clean (Crit. = yes or no)		yes	yes	yes	yes	yes	yes
Staff gages clean (Crit. = yes or no)		yes	yes	yes	yes	yes	yes

RIGHT BANK FISHWAY

Right Bank Entrance:

Head at Entrance (Criteria = 1-2 ft)

RSE-1 (1.5 ft target)	ft	1.3	1.5	1.5	1.4	1.2	1.4
Depth over ladr. weir (Crit. = 1-1.2 ft)	ft	1.1	1.1	1.1	1.0	1.1	1.0
Ladder exit clean (Crit. = yes or no)		yes	yes	yes	yes	yes	yes
Staff gages clean (Crit. = yes or no)		yes	yes	yes	yes	yes	yes

Comment number (if applicable)

Comments: