

Table 9. Pertinent Data for Fish Facility Inspections in 2016 at PRIEST RAPIDS DAM.

CRITERIA ITEMS

LEFT BANK FISHWAY

26-Apr 24-May 23-Jun 27-Jul 24-Aug 28-Sep 25-Oct

Left Bank Entrance:

Head at main entrances (Criteria = 1-2 ft)

LSE-2 (1.2 ft target)	ft	2.0	1.9	1.6	1.7	1.5	1.5	2.0
LSE-4 (1.5 ft target)	ft	1.4	1.6	1.4	1.4	1.8	1.7	1.7
Depth over ladr. weir (Crit. = 1-1.2 ft)	ft	1.1	1.0	1.0	1.1	1	1.0	1.0
Water velocity (Crit. = 1.5-4 fps)	fps	2.0	2.8	2.3	2.5	2.5	1.5	1.9
Ladder exit clean (Crit. = yes or no)		yes	yes	yes	yes	yes	yes	yes
Staff gages clean (Crit. = yes or no)		yes	yes	yes	yes	yes	yes	yes

RIGHT BANK FISHWAY

Right Bank Entrance:

Head at Entrance (Criteria = 1-2 ft)

RSE-1 (1.5 ft target)	ft	1.4	1.2	1.4	1.5	1.4	1.5	1.3
Depth over ladr. weir (Crit. = 1-1.2 ft)	ft	1.2	1.1	1.0	1.2	1.0	1.0	1.0
Ladder exit clean (Crit. = yes or no)		yes	yes	yes	yes	yes	yes	yes
Staff gages clean (Crit. = yes or no)		yes	yes	yes	yes	yes	yes	yes

Comment number (if applicable)

Comments: