

**Table 9. Pertinent Data for Fish Facility Inspections in 2017 at PRIEST RAPIDS DAM.**

<b>CRITERIA ITEMS</b>					
<b>LEFT BANK FISHWAY</b>		<u>25-Apr</u>	<u>24-May</u>	<u>27-Jun</u>	<u>27-Jul</u>
<b><i>Left Bank Entrance:</i></b>					
<b><u>Head at main entrances (Criteria = 1-2 ft)</u></b>					
LSE-2 (1.2 ft target)	ft	1.5	1.9	1.2	2.1
LSE-4 (1.5 ft target)	ft	1.2	1.6	1.2	1.5
Depth over ladr. weir (Crit. = 1-1.2 ft)	ft	1.1	1.1	1.1	1.0
Water velocity (Crit. = 1.5-4 fps)	fps	2.7	2.8	2.3	2.0
Ladder exit clean (Crit. = yes or no)		yes	yes	yes	yes
Staff gages clean (Crit. = yes or no)		yes	yes	yes	no
<b>RIGHT BANK FISHWAY</b>					
<b><i>Right Bank Entrance:</i></b>					
<b><u>Head at Entrance (Criteria = 1-2 ft)</u></b>					
RSE-1 (1.5 ft target)	ft	1.4	1.2	1.5	1.6
Depth over ladr. weir (Crit. = 1-1.2 ft)	ft	1.2	1.1	1.1	1.0
Ladder exit clean (Crit. = yes or no)		yes	yes	yes	yes
Staff gages clean (Crit. = yes or no)		yes	yes	yes	yes
Comment number (if applicable)					
<b>Comments:</b>					