

Table 9. Pertinent Data for Fish Facility Inspections in 2017 at PRIEST RAPIDS DAM.

CRITERIA ITEMS

LEFT BANK FISHWAY

25-Apr 24-May 27-Jun

Left Bank Entrance:

Head at main entrances (Criteria = 1-2 ft)

LSE-2 (1.2 ft target)	ft	1.5	1.9	1.2
LSE-4 (1.5 ft target)	ft	1.2	1.6	1.2
Depth over ladr. weir (Crit. = 1-1.2 ft)	ft	1.1	1.1	1.1
Water velocity (Crit. = 1.5-4 fps)	fps	2.7	2.8	2.3
Ladder exit clean (Crit. = yes or no)		yes	yes	yes
Staff gages clean (Crit. = yes or no)		yes	yes	yes

RIGHT BANK FISHWAY

Right Bank Entrance:

Head at Entrance (Criteria = 1-2 ft)

RSE-1 (1.5 ft target)	ft	1.4	1.2	1.5
Depth over ladr. weir (Crit. = 1-1.2 ft)	ft	1.2	1.1	1.1
Ladder exit clean (Crit. = yes or no)		yes	yes	yes
Staff gages clean (Crit. = yes or no)		yes	yes	yes

Comment number (if applicable)

Comments: