

Table 9. Pertinent Data for Fish Facility Inspections in 2018 at PRIEST RAPIDS DAM.

CRITERIA ITEMS		26-Apr	24-May	26-Jun	19-Jul	22-Aug	12-Sep
LEFT BANK FISHWAY							
<i>Left Bank Entrance:</i>							
<u>Head at main entrances (Criteria = 1-2 ft)</u>							
LSE-2 (1.2 ft target)	ft	1.7	0.8	1.8	1.3	1.1	1.4
LSE-4 (1.5 ft target)	ft	1.5	Na	0.9	1.2	1.3	1.3
Depth over ladr. weir (Crit. = 1-1.2 ft)	ft	1.0	1.1	1.1	1.0	1.1	1.1
Water velocity (Crit. = 1.5-4 fps)	fps	1.2	1.4	2.3	2.5	2.2	1.7
Ladder exit clean (Crit. = yes or no)		yes	yes	yes	yes	yes	yes
Staff gages clean (Crit. = yes or no)		yes	yes	yes	yes	yes	yes
RIGHT BANK FISHWAY							
<i>Right Bank Entrance:</i>							
<u>Head at Entrance (Criteria = 1-2 ft)</u>							
RSE-1 (1.5 ft target)	ft	1.2	Na	1.3	1.3	1.3	1.4
Depth over ladr. weir (Crit. = 1-1.2 ft)	ft	1.0	1.1	1.1	1.2	1.1	0.8
Ladder exit clean (Crit. = yes or no)		yes	yes	yes	yes	yes	yes
Staff gages clean (Crit. = yes or no)		yes	yes	yes	yes	yes	yes
Comment number (if applicable)			1				
Comments:							