

**Table 2. Pertinent Data for Fish Facility Inspections in 2010 at THE DALLES DAM.**

CRITERIA ITEMS		DATE OF INSPECTION					
		3-Mar	29-Apr	28-May	29-Jul	31-Aug	30-Sep
<b>SOUTH SHORE FISHWAY</b>							
<i>East Entrance:</i>							
<b>Depth over entrance weir</b>							
E-1 (gate set at elev. 83.5 ft)	ft	na	10.7	9.9	9.2	8.2	8.5
E-2 (crit. = 8 ft or >)	ft	10.5	11.1	10.9	9.0	8.2	9.0
E-3 (crit. = 8 ft or >)	ft	11.0	10.7	10.9	9.2	8.2	9.5
Head at main entrance (crit. = 1-2 ft)	ft	1.7		1.5	2.1	2.3	2.1
Depth over ladr. weir (crit. = 1-1.3 ft)	ft	1.0	1.0	1.0	1.0	0.9	0.9
Channel Velocity (crit. = 1.5 - 4.0 fps)	fps	3.0	3.0	2.5	2.5	2.5	2.5
Ladder exit clean (yes or no)		yes	yes	yes	yes	yes	yes
Selsyns/PLC operating (yes or no)							
Picket leads clean (yes or no)		yes	yes	yes	yes	yes	yes
<i>West Entrance:</i>							
<b>Depth over entrance weir</b>							
W-1 (crit. = 8 ft or >)	ft	8.2	9.4	9.9	8.4	8.6	8.4
W-2 (crit. = 8 ft or >)	ft	8.1	9.5	10.0	8.6	8.5	8.5
Head at main entrance (crit. = 1-2 ft)	ft	1.5	1.6	1.3	1.1	1.4	1.4
<i>South Entrance:</i>							
<b>Depth over entrance weir</b>							
S-1 (Crit. = 8 ft or >)	ft	8.7	8.2	8.0	8.7	8.1	8.7
S-2 (Crit. = 8 ft or >)	ft	9.2	8.1	8.0	8.4	8.1	8.2
Head at main entrance (Crit. = 1-2 ft)	ft	1.1	1.3	1.2	1.1	1.2	1.1
<b>NORTH SHORE FISHWAY</b>							
<i>North Shore Entrance:</i>							
<b>Depth over entrance weir</b>							
N-1 (crit. = 8 ft or >)	ft	8.7	9.9	9.8	10.4	10.2	na*
Head at main entrance (Crit. = 1-2 ft)	ft	1.1	1.3	1.3	1.2	1.1	na*
Depth over ladr. weir (Crit. = 1-1.3 ft)	ft	1.1	0.9	1.1	1.0	1.0	na*
Ladder exit clean		yes	yes	yes	yes	yes	na*
Selsyns operating							
Picket leads clean		yes	yes	yes	yes	yes	na*
PUD trash rack clean (yes or no)		yes	yes	yes	yes	yes	na*
Spill Pattern w/i Criteria (yes or no)							
							1
<b>Comment Number (if applicable)</b>							
<b>Comments</b>							
1. No access to northside due to construction.							