

Table 2. Pertinent Data for Fish Facility Inspections in 2013 at THE DALLES DAM.

CRITERIA ITEMS		DATE OF INSPECTION							
		<u>21-Mar</u>	<u>25-Apr</u>	<u>22-May</u>	<u>19-Jun</u>	<u>31-Jul</u>	<u>21-Aug</u>	<u>24-Sep</u>	<u>28-Oct</u>
SOUTH SHORE FISHWAY									
East Entrance:									
Depth over entrance weir									
E-1 (gate set at elev. 83.5 ft)	ft								
E-2 (crit. = 8 ft or >)	ft	12.7	13.6	12.9	12.0	11.9	12.9	13.1	11.3
E-3 (crit. = 8 ft or >)	ft	12.6	13.5	12.9	11.9	12.0	12.9	13.0	11.6
Head at main entrance (crit. = 1-2 ft)	ft	1.5	1.5	1.6	1.4	1.6	1.6	1.4	0.6
Depth over ladr. weir (crit. = 1-1.3 ft)	ft	1.0	1.0	1.3	1.3	1.1	1.2	1.1	1.0
Ladder exit clean (yes or no)		yes	yes	yes	yes	yes	yes	yes	yes
Selsyns/PLC operating (yes or no)		yes	yes	yes	yes	yes	yes	yes	yes
Picket leads clean (yes or no)		yes	yes	yes	yes	yes	yes	yes	yes
West Entrance:									
Depth over entrance weir									
W-1 (crit. = 8 ft or >)	ft	OOS		10.0	8.1	8.4	8.2	8.3	8.2
W-2 (crit. = 8 ft or >)	ft	9.5	na	9.9	8.2	8.4	8.1	8.3	8.2
W-3 (crit. = 8 ft or >)	ft	9.5	na	na	na	na	na	na	na
Head at main entrance (crit. = 1-2 ft)	ft	1.5	na	1.7	1.5	1.5	1.1	1.4	1.0
South Entrance:									
Depth over entrance weir									
S-1 (Crit. = 8 ft or >)	ft	8.3	8.3	8.9	9.0	9.0	8.4	8.0	8.1
S-2 (Crit. = 8 ft or >)	ft	8.3	8.3	8.8	9.0	8.9	8.4	8.0	8.2
Head at main entrance (Crit. = 1-2 ft)	ft	1.4	1.4	1.8	1.5	1.5	1.4	1.4	1.1
NORTH SHORE FISHWAY									
North Shore Entrance:									
Depth over entrance weir									
N-1 (crit. = 8 ft or >)	ft	8.8	9.4	8.1	9.1	9.9	9.2	9.7	8.7
Head at main entrance (Crit. = 1-2 ft)	ft	1.4	1.3	1.4	1.3	1.2	1.3	1.2	1.4
Depth over ladr. weir (Crit. = 1-1.3 ft)	ft	1.0	0.8	1.0	1.0	1.0	1.0	1.1	1.0
Ladder exit clean		yes	yes	yes	yes	yes	yes	yes	yes
Selsyns operating		yes	yes	yes	yes	yes	yes	yes	yes
Picket leads clean		yes	yes	yes	yes	yes	yes	yes	yes
PUD trash rack clean (yes or no)		yes	yes	yes	yes	yes	yes	yes	yes
Comment Number (if applicable)		1	2	3	4		5		6
Comments									
1. W-1 is OOS, W-3 being used.									
2. Could not access west entrance gauges.									
3. W-1 back in service.									
4. Junction pool gauge dirty, PUD screen differential high (PUD cleaned).									
5. Junction pool gauge dirty.									
6. Junction Pool staff gauge to dirty to read, east entrance out of criteria.									