

Table 2. Pertinent Data for Fish Facility Inspections in 2015 at THE DALLES DAM.

CRITERIA ITEMS	DATE OF INSPECTION							
		<u>24-Mar</u>	<u>28-Apr</u>	<u>29-May</u>	<u>26-Jun</u>	<u>4-Aug</u>	<u>24-Sep</u>	<u>26-Oct</u>
SOUTH SHORE FISHWAY								
<i>East Entrance:</i>								
Depth over entrance weir								
E-1 (gate set at elev. 83.5 ft)	ft	na	na	na	na	na	na	na
E-2 (crit. = 8 ft or >)	ft	12.1	12.6	12.5	11.1	12.1	12.0	11.2
E-3 (crit. = 8 ft or >)	ft	11.8	10.6	13.4	11.2	12.9	12.0	10.1
Head at main entrance (crit. = 1-2 ft)	ft	1.6	1.5	1.4	1.5	-0.7	1.2	1.5
Depth over ladr. weir (crit. = 1-1.3 ft)	ft	1.0	1.0	1.1	1.3	1.0	1.1	1.1
Ladder exit clean (yes or no)		yes	yes	yes	yes	yes	yes	yes
Selsyns/PLC operating (yes or no)		yes	yes	yes	yes	yes	yes	yes
Picket leads clean (yes or no)		yes	yes	yes	yes	yes	yes	yes
<i>West Entrance:</i>								
Depth over entrance weir								
W-1 (crit. = 8 ft or >)	ft	12.0	10.2	9.9	9.1	9.5	10.2	9.1
W-2 (crit. = 8 ft or >)	ft	12.0	9.9	10.0	9.0	9.6	10.2	9.1
W-3 (crit. = 8 ft or >)	ft	na	na	na	na	na	na	na
Head at main entrance (crit. = 1-2 ft)	ft	1.4	1.8	1.5	1.6	0.0	1.6	1.6
<i>South Entrance:</i>								
Depth over entrance weir								
S-1 (Crit. = 8 ft or >)	ft	9.5	8.5	8.2	8.3	8.3	8.5	8.4
S-2 (Crit. = 8 ft or >)	ft	9.4	8.5	8.2	8.3	8.3	8.5	8.4
Head at main entrance (Crit. = 1-2 ft)	ft	1.4	1.4	1.4	1.4	0.1	1.5	1.4
NORTH SHORE FISHWAY								
<i>North Shore Entrance:</i>								
Depth over entrance weir								
N-1 (crit. = 8 ft or >)	ft	9.5	9.7	9.5	9.3	9.2	9.4	8.4
Head at main entrance (Crit. = 1-2 ft)	ft	1.4	1.2	1.4	1.4	1.1	1.3	1.4
Depth over ladr. weir (Crit. = 1-1.3 ft)	ft	1.0	1.0	1.0	0.9	1.1	1.0	1.1
Ladder exit clean		yes	yes	yes	yes	yes	yes	yes
Selsyns operating		yes	yes	yes	yes	yes	yes	yes
Picket leads clean		yes	yes	yes	yes	yes	yes	yes
PUD trash rack clean (yes or no)		yes	yes	yes	yes	yes	yes	yes
Comment Number (if applicable)								
Comments						1	2	
1. ROV inspection for east fishway all entrances out of criteria, east entrance was blocked at Jnxn pool (negative differential), both F1 and F2 OOS for ROV, PUD offline for maintenance.								
2. Two over size sturgeon below north count station.								